



































1  =11	2  =2	3  =12	4  5X50mm =24	5  =11	6  =1	7  =1	8  =23	9  4x25mm =2
10  =1	11  =10	12  =1	13  =12	14  M6x20 =24	15  1100 =1	16  =13	17  =1	18  6X80 =9
19  =2	20  =1	21  =1	22  =26	23  =12	24  =1	25  =2	26  =1	27  =1
28  =1	29  =12	30  888 =12	31  4x30 =24	32  =12	33  =12	34  M 6X50 =12		

1  =1	2  =1	3  5X50mm =1	4  4x30mm =3	5  =1	6  =1	7  M6 x 20 D140 =6 D160 =7	8  =1	9  D140 =6 D160 =7
10  D140 =6 D160 =7	11  D140 =6 D160 =7	12  M6 x 45 D140 =6 D160 =7	13  =3	14  5x25mm =6	15  6X80mm =6	16  =7	17  Ø10 =8	18  =1
19  =1	20  4,2x13mm =2	21  5x40mm =2	22  =1	23  =1	24  =2			